


SURFMK

- Turn off power before installation.
- Refer to panel light instructions for connections.

Pack Contents:


 1 x Surface mounting box
 8 x Screws


STEP 1




Fix the 2 x "L" shape parts and 1 x "U" shaped part together, using 4 of the screws supplied.

STEP 2




Fix the now assembled frame on to the ceiling using 4 x screws and raw plugs (not supplied).

STEP 3




Connect the wires between the driver and the AC end. Refer to panel light instructions for connections.

STEP 4




Connect the DC cable on the driver to the panel light.

STEP 5



Push the panel light into the surface mounted frame, making sure the driver is on the reverse of the panel.

STEP 6



Attach the remaining "L" shaped part on to the frame and lock tightly using the remaining 4 x screws supplied.